





CUP HEAD PIN - APPLICATION




1. HANG INSULATION



2. PRESS CUPHEAD PIN THROUGH INSULATION.

Note: an insulating paper washer is required here when welding through foil faced insulation.



3. WELD IN PLACE TO COMPLETE INSTALLATION

www.sunbeltstudwelding.com

Sunbelt Stud Welding, Inc
6381 Windfern Road
Houston, Texas 77040-4915



1-800-462-9353
713-939-8903
fax 713-939-9013