


CABLE HANGERS: TAPPED/TUBULAR TYPE

TAPPED CABLE HANGER	
CATALOG #	LENGTH-A (INCHES)
0150	1.50
0250	2.50
0350	3.50
0450	4.50
0550	5.50
0650	6.50
0750	7.50

7/8" X 3/8" RECTANGULAR



Fastening a Tapped Cable Hanger is Easy

1. Weld a standard 3/8" or M10 diameter weld stud.
2. Spin desired cable hanger onto the weld stud.
3. Attach cable either by: *crimping* hanger or *banding* to hanger.

Available in 316SS

www.sunbeltstudwelding.com

Sunbelt Stud Welding, Inc.
6381 Windfern Road
Houston, Texas 77040-4915



15-12

1-800-462-9353
713-939-8903
fax 713-939-9013