




CABLE HANGERS: TAPPED-PLATE TYPE


TAPPED CABLE HANGER	
CATALOG #	LENGTH-A INCHES
15002	2
15003	3
15004	4
15006	6
15008	8

BOTTOM LOADING



TAPPED CABLE HANGER	
CATALOG #	LENGTH-A INCHES
16002	2
16003	3
16004	4
16006	6
16008	8

(INVERTED) TOP LOADING



Fastening a Tapped Cable Hanger is Easy

1. Weld a standard 3/8" or M10 diameter weld stud.
2. Spin desired cable hanger onto the weld stud.
3. Attach cables either by: *crimping* hanger or *banding* to hanger.

Available in 316SS

www.sunbeltstudwelding.com

Sunbelt Stud Welding, Inc
6381 Windfern Road
Houston, Texas 77040-4915

